

Lesen Sie die Gebrauchsanweisung vor der Verarbeitung aufmerksam durch.

- 1 Reinigen Sie den Bereich, auf den die SPLASH-Caps geklebt werden sollen gründlich von Staub-, Schmutz-, Fett oder Politurrückständen (ggf. mit Silikon-Entferner).

Achtung: Der Spritzstrahl darf nicht durch die Positionierung der Caps beeinträchtigt werden!

- 2 Entfernen Sie die Schutzfolie von den Klebepads und drücken Sie die Caps fest an.

Hinweis:

Die volle Klebkraft der Pads ist nach 24 Stunden erreicht. Bitte in dieser Zeit trocken halten und nicht belasten.

Please read the instruction manual carefully before usage.

- 1 Thoroughly clean the application surface from grease, dirt, dust, polish residue etc. (with silikon remover for example).

Attention:

The positioning of the caps may not impair the squirted stream!

- 2 Remove the protective foil from the adhesive pads and apply firm pressure to the caps.

Note:

The full adhesive effect of the pads is achieved after 24 hours. Please keep dry and do not burden during this time.

SPLASH
CAPS

FOLIATEC.com

MONAGEANLEITUNG • INSTALLATION INSTRUCTION

FOLIATEC Böhm GmbH & Co Vertriebs KG
Neumeyerstr. 70, 90411 Nürnberg, Germany
Tel.: +49(0)911/97544-0
Fax: +49(0)911/97544-333
techsupport@foliatec.de
www.foliatec.com